

Building Conservation

mortar.

We have a wealth of experience in managing and delivering specialist historic repair and building conservation projects which demand a unique focus and sympathetic attention to ensure our region's built heritage is maintained and conserved.

Dunstanburgh Castle

Works to this Grade I* lisited building and

scheduled ancient monument involved the removal of loose stone and mortar to antici-

pate its accidental fall. Structurally damaged

included raking out mortar joints, filling and

stone was selectivly replaced. Other elements

consolidating cavities and re-pointing. toric lime





1 The Theatre Royal

The project focussed on the careful repair and conservation of the theatre's external façade, specifically the Portico and front elevation. Works comprised stone indentation, mortar based repairs, re-pointing, limited gentle cleaning and removal of bird guano. The external works formed part of a larger award winning packcage.






The Castle Keep

St Astier undertook three phases of work to the Castle Keep. The phases addressed the replacement of 160 structurally failing natural stone blocks along with large areas of historic lime repointing, repairs and the intallation of drainage falls to the roof, and finally, deshaling and the reinstatement of architectural features designed to shed water away from the structure.



Spanish City Dome

Essential repair and cleaning works were carried out to this Grade II listed iconic coastal building as the Ferro-crete dome had suffered deterioration at the hands of the North Sea wind and rain. Existing coatings were removed from the concrete dome which was then repaired and protected using specialist concrete repair systems.





Statue of Sir Charles Palmer

An award winning building conservation scheme to remove, restore and relocate the statue of Sir Charles Mark Palmer to make way for the new Tyne Crossing. Stone repairs were undertaken to the base and pedestal whilst corrosion was gently removed from bronze statue before it was cleaned, repatinated and protected prior to the structure being rebuilt at its new location.





