

27th August, 2012

To our valued customers

Issue on Selfer Hydraulic Pump HPD-05

Since 1st July, 2006, we have supplied the machine tool products compliant with the RoHS directive, but have found that the vinyl cord (ground wire) and the Suction Filter for the Selfer Hydraulic Pump “HPD-05” were not.

We herewith report to you, and apologize for any inconvenience caused on this matter.

We kindly ask you to contact your local distributor or our subsidiary company in Europe for repair of the applicable products.

Best regards,

Atsushi Shirai

Executive Director, Engineering

Object Products and serial numbers:

| HPD-05 110V-120V CE |
|--|
| Produced Jun. 2006 ~ Dec. 2011 75 units |
| 0700183 ~ 0700188 |
| 0700332 ~ 0700335 |
| 0700349 ~ 0700354 |
| 0800024 ~ 0800027 |
| 0800051 ~ 0800056 |
| 0800114 ~ 0800121 |
| 0800167 ~ 0800171 |
| 0800202 ~ 0800211 |
| 0800262 ~ 0800276 |
| 0800338 ~ 0800342 |
| 0800378 ~ 0800387 |
| 0800393 ~ 0800397 |
| 0000041 ~ 0000050 |
| 0000086 ~ 0000095 |
| 0100027 ~ 0100029 |

| HPD-05 220V-240V CE |
|---|
| Produced Jun. 2006 ~ Dec. 2011 107 units |
| 0600146 ~ 0600150 |
| 0700050 ~ 0700057 |
| 0700189 ~ 0700192 |
| 0700330 ~ 0700331 |
| 0700346 ~ 0700348 |
| 0800028 ~ 0800030 |
| 0800122 ~ 0800131 |
| 0800172 ~ 0800176 |
| 0800212 ~ 0800216 |
| 0800241 ~ 0800250 |
| 0800277 ~ 0800281 |
| 0800368 ~ 0800377 |
| 0000071 ~ 0000075 |
| |
| |

Contact address:

NITTO KOHKI EUROPE CO., LTD.

Unit 21, The Empire Centre, Imperial Way, Watford Hertfordshire,
WD24 4TS, United Kingdom

TEL : +44-1923-239668

NITTO KOHKI DEUTSCHLAND GMBH

Lerchenstrasse 47, D-71144 Steinenbronn, Germany

TEL : +49-7157-22436