CONVERSION TABLE

	TO CONVERT FROM	ТО	MULTIPLY BY
M A S S	LB (Avoirdupois) LB (Avoirdupois) OZ (Avoirdupois) SLUG TON (2000 LB) TON (Metric)	KG GM GM KG KG KG	.45359 453.59 28.35 14.594 907.18 1000
т	TO CONVERT FROM	то	MULTIPLY BY
E M P	°F °C °C °F	°C °F °K °R	$t^{\circ}_{c} = (t^{\circ}_{f} - 32) / 1.8$ $t^{\circ}_{f} = (1.8)(t^{\circ}_{c}) + 32$ $t^{\circ}_{k} = t^{\circ}_{c} + 273.15$ $t^{\circ}_{R} = t^{\circ}_{f} + 459.67$
	TO CONVERT FROM	то	MULTIPLY BY
TORQUE	LB-IN LB-FT OZ-FT OZ-FT KG-M OZ-IN KG-M DYNE-CM DYNE-CM	N-M N-M LB-IN N-M GM-CM LB-IN OZ-IN N-M	.11298 1.3558 8.4739 X 10 ⁻² .75 9.8067 72.008 86.796 1.4161 X 10 ⁻⁵ 1 X 10 ⁻⁷
	TO CONVERT FROM	то	MULTIPLY BY
L E N G T H	CM FT IN IN M M	IN M MM CM FT IN	0.3937 .305 25.4 2.54 3.281 39.37