



# Cooling Tower Leak Repairs

We specialise in permanent repairs



Typical sealant failure




Characteristic 'curtaining'

Any manufacturer  
Any model  
Nationwide

Our leak repair system:

- Ensures the water remains in the cooling tower
- Avoids consequential loss of water treatment chemicals or regime control
- Prevents build-up of external deposits
- Eliminates leak derived algae proliferation
- Prevents slippery/icy adjacent working area



Tower Systems permanent repair

## Leak repair products

Stainless steel leak repair profiles, neoprene corded butyl sealer tape, single part polyurethane caulking.



For more information or to arrange a site survey, please call us on **01923 238603**

or email [info@towersystems.co.uk](mailto:info@towersystems.co.uk)



Tower Systems Ltd • Unit 4 Sandown Road • Watford • Herts WD24 7UB  
Tel: 01923 238603 • Fax: 01923 239093 • E-mail: [info@towersystems.co.uk](mailto:info@towersystems.co.uk)



[www.towersystems.co.uk](http://www.towersystems.co.uk)