




Universal

Specialist in Rotating Electrics



Nissan Micra & Note 1.2 2011>



UNA2881 Alternator

12 Volt 100 amp

PV7 pulley

Lucas LRA03664

OE refs:

NISSAN 23100-1HH1A

NISSAN 23100-1HN1A

MITSUBISHI A5TL0191

MITSUBISHI A5TL0191A

New to Range
Only **£** ring for details



Plug 99

STOP START
STARTERS AND ALTERNATORS



UNS1941 Starter

12 Volt 1.0kw 9 tooth

Lucas LRS02687


OE refs:

NISSAN 23300-1HC1A

NISSAN 1196052A

VALEO FS10M3

New to Range
Only **£** ring for details



Vehicle recall Warning!!

The push start ignition switch on the K13 series Micra (2010 -onwards) has a known fault, causing the switch to remain in the pressed position and not return after the engine is switched on. The fault can result in the starter motor not disengaging and burning out. Please check the old starter motor for this type of damage.