

## **BA Series** Rupture Disk Burst Sensor

# Over pressure indication for rupture disk or relief valve applications

When a pressure surge causes a relief valve to open, it also destroys the rupture disk under the valve. This leaves the valve vulnerable to chemical attack. The BA Burst Sensor reduces this threat by constantly monitoring the disk. When connected to an electrical alarm, the BA Burst Sensor alerts personnel to take immediate action to protect system components from further damage.

#### Operation

When a disk bursts, flow pulls one end of the BA Burst Sensor's conductor out of its retaining slot and opens the electrical circuit. The BA Burst Sensor can be reset by re-inserting the conductor into the retaining slot.

### Features

- Re-Settable
- Sizes 1" thru 24"
- Electrically conductive
- Installs on vent side of the disk holder or alone
- Requires minimal flange face-to-face clearanc
- Adapts to virtually all makes/types of rupture disks, including Graphite types
- Fits easily into existing pipe systems
- Optional leak detection (BA-LD) for damaged rupture disks or fugitive emissions from relief valves or atmospheric designed systems
- BA-LD functions with or without a rupture disk

BA Operating Limits		
Max. Temperature	700°F	
Max. Continuous Temp	400°F	
Max. Voltage	24 VDC	
Max. Current	20 mA	

#### Specification

Disk Size	Minimum Burst Pressure* psi @ 72°F (22°C)	Nominal Indicator Thickness	Thickness with Optional LD
1" - 2"	5	2/40"	
3"	3		1/4"
4"	2	3/16"	1/4
6" - 24"	1		

\*If burst pressures are near the min, if flow or volume is low, or if detection is critical, we recommend redundant indication or the consideration of other ZOOK indicators (Applies to both BA and BA-LD). Please consult your local ZOOK representative or contact us at sales@zookdisk.com. 316SS 3-dimensional tag


9" lead wire (standard)

> 9" to 500' shielded cable (optional)

316SS conductor (standard)

Non-asbestos gaskets (standard)

Moisture and abrasion resistant connector features two-pin bullet terminal



**Note:** BA and BA-LD is considered a simple device, therefore, approval is not required. Installation must be in accordance with ANSI/ISA RP12.6 and the NEC (ANSI/NFPA 70)

#### Ordering Information


When ordering BA Series, specify: flange size, flange series relieving pressure or pressure relief device, and coincident temperature




## Safety through knowledge and performance.

## **BA Series Specifications**

### Optional Leak Detector (LD) for BA Burst Sensor



Relief Valve with BA and BA-LD Burst Sensor Applications




### Monitor

The BA Burst Sensor works with ZOOK ZAM Plus Alarm Monitor or any other monitoring system. Consult ZOOK for additional information. The monitor wired to the BA Burst Sensor will be activated providing immediate local or remote warning of a ruptured disk. The ZAM Plus monitor allows output to control pumps, valves, and other equipment which may be activated to control or shutdown a process.

#### CAUTION

The BA Burst Sensor is an electrical device suitable for use in hazardous locations (Class I, II, and III, Division 1 and 2, Group A thru G) provided that it is used with an approved intrinsically safe electrical alarm monitor. For services involving highly electrically conductive fluids, consult the ZOOK factory for this type of application.



\*Contact ZOOK for information about mounting the ZAM Plus Alarm Monitor in hazardous locations ▲Hazardous location equipment must be NEC compliant or simple apparatus.



## Visit us at www.zookdisk.com

#### SERVING AMERICA, CENTRAL SERVING EUROPE, & SOUTH AMERICA

16809 Park Circle Drive Chagrin Falls, Ohio 44022 United States

Toll Free: +1 800 543 1043 Phone: +1 440 543 1010 Fax: +1 440 543 4930 E-mail: sales@zookdisk.com

## **MIDDLE EAST & AFRICA**

Navigation House, Bridge St. Killamarsh, Sheffield, S21 1AL United Kingdom Phone: +44 (0) 1909 560999

Fax: +44 (0) 1909 560860 E-mail: sales.europe@zookdisk.com

## SERVING

## CANADA

4400 South Service Road Burlington, Ontario, L7L 5R8 Canada Toll Free: +1 800 370 6057 Phone: +1 905 681 2885

Fax: +1 905 681 8838 E-mail: sales.canada@zookdisk.com E-mail: sales.asia@zookdisk.com

#### SERVING **ASIA PACIFIC**

Unit No. 23A-05, Menara Landmark No.12, Jalan Ngee Heng 80000 Johor Bahru, Johor, Malaysia Phone: +60 (7) 2910099 Fax: +60 (7) 2910096

