


TILE DOCTOR CASE HISTORY

PROJECT: Reveal, Clean and Seal an original Victorian floor where the floor had been covered with Linoleum and Carpet for over 50 years.



You can see from the pictures, the floor had been covered first old plastic vinyl which had been glued down with a strong adhesive and then later with a carpet.

The customer had tried removing the vinyl themselves to reveal the real floor but gave up after eight hours and called in TileDoctor.

Removing the Vinyl was arduous work and care was required not to damage the floor underneath. Naturally we managed and then had to contend with the rubber matting that the vinyl was stuck to and this proved to be even harder to lift.



To remove the rubber matting and adhesive the whole floor had to be covered with a special product that breaks down the glue.



Once the rubber had been disposed of we got down to cleaning the floor and removed any remaining stubborn marks.

Finally we sealed the floor to protect it.



As you can see from the comment above the customer was ecstatic with the result.

*Just got the second e-mail with the photos - they are great and really show how much hard work went into the job. As I said, we did get several "tile experts" in to look at the job and they wouldn't touch the lino, so well done and many thanks again - would definitely recommend you to prospective customers
Regards John*

